

Repair Order

Doc Number: 42048 Service Writer: JON SEGHI Date Printed: 02/27/2019 Date Promised: 10/06/2017 Date In: 10/06/2017 Cashier: MICHAEL UNGUREANU Cashier Date: 12/28/2017

Customer Information

Home Phone: 818-705-4430 Cell Phone: 818-400-4707 Email: DHAFT@SBCGLOBAL.NET

	- Fold Here		
nit 2018 BMW K1600GTL	Color:LIGHT WHITE	Keyboard:	
VIN/SerialWB10F1202JZD91280	Plate:	Odom/Hrs 2,412	Out: 2,438
792 - C/S THAT WHEN STARTING THE MOTORC	YCLE IT REVS TO ABOUT 450	00 RPM / THROTTLE	
Description: TESTED THROTTLE BODY FAULT CODE 3A1421 @ 3882 FAULT CODE 3A1423 @ 3778			
THROTTLE VALVE 1 Description	Technician	Hour	Tota
SEE ORIGINAL W/O	ROBERT HOLLINS	WARRANTY	WARRAN
R&I THROTTLE VALVE ASSEM	ROBERT HOLLINS	WARRANTY	WARRAN
		Labor Subtotal	WARRANT
		Job Subtotal	WARRAN
		All Jobs Subtotal:	\$0.
		Total:	\$0.
		Less Deposits:	\$0.
		Less Deposits: Total Due:	\$0 \$0

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OR WARRANTIES: Any warranties on the products sold hereby are those made by the manufactures. The seller here expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

Any motorcycle not picked up after 3 business days from the date of notification of completion will be assessed a storage fee of \$75 per day.

Motorcycles for repair will be stored outside during normal business hours. If you do not want your motorcycle exposed to the outside elements you are required to provide a cover for your motorcycle.

I hereby acknowledge that I was notified & gave oral approval of the above estimate: I hereby acknowledge receiving estimate of repairs:

Signature:

