



2913 N. Ontario St., Burbank, CA 91504  
 818-446-2450 www.bmwburbank.com  
 BAR#283757 EPA ID#CAL000417063

# Repair Order Invoice

**Doc Number:** 41772  
**Service Writer:** JON SEGHI  
**Date Printed:** 02/27/2019  
**Date Promised:** 08/23/2017  
**Date In:** 08/23/2017  
**Cashier:** JON SEGHI  
**Cashier Date:** 08/23/2017

**DANIEL MORDECAI HAFT**  
~~8754 BIANCA AVE.~~  
~~ENCINO, CA 91436~~

**Customer Information**

**Home Phone:** 818-705-4430  
**Cell Phone:** 818-400-4707  
**Email:** DHAFT@SBCGLOBAL.NET

Fold Here

## Summary

Unit	Job	Job Total
2018 BMW K1600GTL	C/S THROTTLE HAS NOT WORKED TWICE	<b>WARRANTY</b>

<b>Job Subtotal:</b>	<b>\$0.00</b>
<b>Total:</b>	<b>\$0.00</b>
<b>Less Deposits:</b>	<b>\$0.00</b>
<b>Total Due:</b>	<b>\$0.00</b>

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OR WARRANTIES: Any warranties on the products sold hereby are those made by the manufactures. The seller here expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

\*\*\*Any motorcycle not picked up after 3 business days from the date of notification of completion will be assessed a storage fee of \$75 per day.\*\*\*

\*\*\*Motorcycles for repair will be stored outside during normal business hours. If you do not want your motorcycle exposed to the outside elements you are required to provide a cover for your motorcycle.\*\*\*

I hereby acknowledge that I was notified & gave oral approval of the above estimate: I hereby acknowledge receiving estimate of repairs:

**Signature:** \_\_\_\_\_

# Detail

Unit 2018 BMW K1600GTL

Color: LIGHT WHITE

Keyboard:

VIN/Serial WB10F1202JZD91280

Plate:

Odom/Hrs 2,230

Out: 2,231

## 509 - C/S THROTTLE HAS NOT WORKED TWICE

Description:

Description	Technician	Hour	Total
	COLE LEVERTON	WARRANTY	WARRANTY
<b>Labor Subtotal</b>			<b>WARRANTY</b>

**Job Subtotal** WARRANTY

**All Jobs Subtotal:** \$0.00

**Total:** \$0.00

**Less Deposits:** \$0.00

**Total Due:** \$0.00

